


1998 Lexus LS400

Submodel: | Engine Type: V8 | Liters: 4.0
Fuel Delivery: FI | Fuel: GAS



8E09-01

INSPECTION
INSPECTION TRANSPONDER KEY COIL CONTINUITY
Check that there is continuity between terminal 1 and 2.
If continuity is not as specified, replace the coil.