## **REASSEMBLY**

BR0MQ-04

Reassembly is in the reverse order of disassembly (See page BR-12).

HINT:

Apply lithium soap base glycol grease to the rubber parts indicated by the arrows (See page BR-10).

2005 LEXUS IS300 (RM1140U)

Author: Date: 1817