INSPECTION

HINT:

The SRS wire harness is integrated with the instrument panel wire harness assembly. All the connectors in the system are a standard yellow color.

1. Vehicles not involved in collision:

INSPECT SUPPLEMENTAL RESTRAINT SYSTEM

Perform a diagnostic system check (See page DI-607).

2. Vehicles involved in collision:

INSPECT SUPPLEMENTAL RESTRAINT SYSTEM

- (a) Perform a diagnostic system check (See page DI-607).
- (b) Check breaks in all wires of the SRS wire harness, and exposed conductors.
- (c) Check to see if the SRS wire harness connectors are cracked or chipped.

Author:

Date:

2000

2005 LEXUS IS300 (RM1140U)