


■ MULTIPLEX COMMUNICATION SYSTEM

1. Major Difference

In accordance with the adoption of a new model HDD navigation system, the configuration of the AVC-LAN and MOST has been changed and the parking assist ECU has been discontinued.



08E5NF13C

*1: Option

*2: Models with Multi-media Module Display

*3: Models without Multi-media Module Display

*4: Models with Double Locking System