PROPELLER SHAFT SERVICE DATA

SS132-01

Shaft runout Max.	0.8 mm (0.031 in.)
Joint angle (No. 2 joint)	- 1° 21' ± 30'
Joint angle (No. 3 joint)	2° 18' ± 30'
Center support bearing adjusting washer thickness	2.0 mm (0.079 in.)
	4.5 mm (0.177 in.)
	6.5 mm (0.256 in.)
	9.0 mm (0.354 in.)
	11.0 mm (0.433 in.)
	13.5 mm (0.531 in.)

2005 LEXUS IS300 (RM1140U)

Author: Date: 173